

Federal Energy Act Report

October 1, 2014 thru September 30, 2015

(Public Record Posted Date: November 18, 2015)

General Information:

Total Number of Active UST Facilities: **6,942**
Total Number of Active/Inactive USTs: **19,740**

Summary Information For On-Site Inspections:

Number of UST Facilities Inspected: **3,300**
Percent of UST Facilities in SOC Compliance: **66**

Note:

Facility and tank information is based on onsite inspections of all active regulated UST facilities and covers all active/inactive tanks at those facilities. Active regulated Illinois UST facilities are inspected on a two year cycle. Onsite inspections measure compliance against Illinois UST requirements at 41 Illinois Administrative Code Parts 174, 175, 176 & 177 and federal UST regulations at 40 CFR Part 280.

Summary Information For Releases:

Number of Confirmed UST Releases: **309**

Sources and Causes of Environmental Releases from Underground Storage Tanks in Illinois

Source			Cause													
			Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	163	52.8	0	0	0	0	2	0	104	0	0	0	7	0	50	16.2
Piping	26	8.4	0	0	0	0	2	0	13	0	0	0	0	0	11	3.6
Dispenser	3	1	0	0	0	0	1	0	2	0	0	0	0	0	0	0
Submersible (STP)	3	1	0	0	0	0	0	0	0	0	0	0	0	0	3	1
Delivery Problem	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Unknown	114	36.9	0	0	0	0	0	0	0	0	0	0	0	0	114	0
Other	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Totals	309	100	0	0	0	0	5	0	119	0	0	0	7	0	178	20.8

(source of data: Illinois Environmental Protection Agency)

To view site specific information at the Office of the State Fire Marshal, please visit: <http://webapps.sfm.illinois.gov/ustsearch/>

To view the LUST Incident Tracking Database, please visit: <http://epadata.epa.state.il.us/land/ust/Search.asp>

Revised 5/11/16